


DETAIL SHOWING METHOD OF JOINING TRACK SECTIONS

M8 BOLTS

PINS



NOTE: THE FOLLOWING ITEMS ARE SECURED BY M8 BOLTS WITH NUTS TO SUIT, (B-A) (C-A) (E-A) (F-A)

- A) T70 Straight Section
- B) T70 Hand Line Head Pulley
- C) T70 Return Pulley
- D) T70 M12 x 150mm Stud
- E) T70 Universal Clamp
- F) T70 Overlap Clip
- G) T70 Master Carrier
- H) T70 Wheeled Runner
- I) T70 Face Fixing Bracket
- J) T70 End Stop

